OMB Control No.: 2127-0004

Part 573 Safety Recall Report

19V-813

Manufacturer Name: Chrysler (FCA US LLC)

NHTSA Recall No.: 19V-813

Manufacturer Recall No.: V62



Manufacturer Information:

Manufacturer Name: Chrysler (FCA US LLC)

Address: 800 Chrysler Drive

CIMS 482-00-91 Auburn Hills MI

48326-2757

Company phone: 1-800-853-1403

Population:

Number of potentially involved : 528,594 Estimated percentage with defect : 100 %

Vehicle Information:

Vehicle 1: 2011-2013 Dodge Durango

Vehicle Type:

Body Style: SUV Power Train: NR

Descriptive Information: Some 2011 through 2013 MY Dodge Durango vehicles that are included in the NHTSA

Recalls 14V-530 and 15V-115 vehicle population may have had a fuel pump relay installed as a recall remedy that is susceptible to silicon contamination of the relay

contacts that can cause the relay to fail.

The vehicle population was determined to be all vehicles that are included for NHTSA Recalls 14V-530 and 15V-115, including all remedied and unremedied vehicles.

Similar vehicles not included in this recall were not included in recalls 14V-530 or

15V-115.

The total affected vehicles for this model is 147,846.

Production Dates: AUG 23, 2010 - AUG 19, 2013

Vehicle 2: 2011-2013 Jeep Grand Cherokee

Vehicle Type:

Body Style : SUV Power Train : NR

Descriptive Information: Some 2011 through 2013 MY Jeep Grand Cherokee vehicles that are included in the

NHTSA Recalls 14V-530 and 15V-115 vehicle population may have had a fuel pump relay installed as a recall remedy that is susceptible to silicon contamination of the

relay contacts that can cause the relay to fail.

The vehicle population was determined to be all vehicles that are included for NHTSA

Not sequential

Recalls 14V-530 and 15V-115, including all remedied and unremedied vehicles.

Similar vehicles not included in this recall were not included in recalls 14V-530 or 15V-115.

The total affected vehicles for this model is 380.748.

Production Dates: FEB 24, 2010 - JAN 19, 2013

VIN Range 1: Begin: NR End: NR

Description of Defect:

Description of the Defect: A fuel pump relay failure can result in a stall condition if the vehicle is running

or a no-start condition if not running.

FMVSS 1: NR

FMVSS 2: NR

Description of the Safety Risk: A vehicle stall while driving can cause a vehicle crash without prior warning.

Description of the Cause: NR

Identification of Any Warning Some vehicles may experience an extended engine crank time or require

that can Occur: multiple start attempts prior to experiencing an engine stall event while

driving.

Supplier Identification:

Component Manufacturer

Name: NR

Address: NR

NR

Country: NR

Chronology:

Please see attached supplemental information titled "FCA US LLC Chronology - V62 2011-2013 Dodge Durango and Jeep Grand Cherokee Fuel Pump Relay 11142019.pdf".

Description of Remedy:

Description of Remedy Program: FCA US will conduct a Voluntary Safety Recall on affected vehicles. The

remedy is currently under development.

FCA US has a longstanding policy and practice of reimbursing owners who have incurred the cost of repairing a problem that subsequently becomes the subject of a field action. To ensure consistency, FCA US, as part of the owner letter, will request that customers send the original receipt and/or other adequate proof of payment to the company for confirmation of the

expense.

from Recalled Component:

How Remedy Component Differs Part Name: Relay wiring / Relay wiring

Part Description: External fuel pump relay package / External fuel pump

relay package

Part Number: CBWPR091AA / CBP4P541AB

Part Comment: The remedy is under development.

Identify How/When Recall Condition NR was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: **11/14/2019: FCA US will notify dealers and begin notifying owners on

or about 01/03/2020.

Planned Dealer Notification Date: JAN 03, 2020 - JAN 03, 2020 Planned Owner Notification Date: JAN 03, 2020 - JAN 03, 2020

* NR - Not Reported